Diagnostic Report

THINKCAR

SN: 9TDP80613518

Time: October 29, 2026 09:44:11

Customer Name: [redacted]

Technician Name: Kim Makynen

McYnen

Shop Name: Autohuoltomies McYnen / Ab McYnen Oy	Telephone: 0503557741
Email: makynen@mac.com	Country: N/A
State: N/A	City: N/A
Address1: Karhumetsantie 11, 65610 Mustasaari	Address2: N/A

Make: BENZ	Model: 204.282 - C 250 CDI 4MATIC BlueEFFICIENCY Wagon, C 250 CDI 4MATIC Wagon
Year: 2012	VIN: WDD204[redacted]
Odometer: 393303 km	License #: [redacted]

Pre-Scan

October 29, 2026 09:44:11

System(34)	**Status(5)**
ECM - Engine Control Module(CDI)	Fault | 2
FSCU - Control Unit'Fuel pump'(N118)	No Fault
ESM[EWM] - Electronic Selector module(N15/5)	No Fault
TCM - Transmission Control Module	No Fault
ESP - Electronic Stability program(N30/4)	No Fault
IRS-HRA - Outer Right Rear Intelligent Radar Sensor system(B29/5)	No Fault

IRS-HLA - Outer Left Rear Intelligent Radar Sensor system(B29/4)	Fault | 1
MFK - Multifunction camera(A40/11)	No Fault
EZS - Electronic Ignition lock(N73)	No Fault
SCM - Steering Column Module	No Fault
Driver-side SAM - Front Signal Acquisition And Actuation Module	No Fault
REAR SAM - Rear Signal Acquisition And Actuation Module	No Fault
SRS - Supplemental Inflatable Restraint System	No Fault
AHE - Trailer Recognition	No Fault
CGW[ZGW] - Central Gateway	No Fault
SG-SW - Control Unit 'Headlamp'(N71/1)	No Fault
COU[ZBE] - Audio/COMAND Operating Unit	No Fault
ZAN - Audio/COMAND Display	No Fault
Audio/COMAND - Audio Or COMAND(A2-A2/56-A40/3)	Fault | 1
IC - Instrument cluster(A1)	Fault | 1
MIF - Media Interface	No Fault
NAV - Navigation Module	No Fault
DCU_LR - Left Rear door(N69/3)	No Fault
DCU_RR - Right Rear door(N69/4)	No Fault
DCU_LF - Left Front door(N69/1)	No Fault
DCU_RF - Right Front door(N69/2)	No Fault
AC - Air Conditioning(N22/7)	No Fault

LIN: M6/1 - Windshield wiper(FSW)	No Fault
LIN: B38/2 - Rain/Light sensor(RGLS)	No Fault
LIN: B95 - Battery sensor(BSN)	No Fault
LIN: R13/1,R13/2,R13/3,R13/4 - Seat heater(SIH)	No Fault
LIN: E1n7 - Actuation Module, LED Exterior Lighting, Left front(AMLAB-L)	No Fault
LIN: E2n7 - Actuation Module, LED Exterior Lighting, Right front(AMLAB-R)	No Fault
LIN: S55/2 - Switch Group '' Right Rear Seat adjustment''(SSE-RR)	No Fault

DTC

System	Code	Description	Status
ECM - Engine Control Module(CDI)	P200A75	The charge movement flap (cylinder bank 1) has a malfunction.The emergency position was not reached.	STORED
ECM - Engine Control Module(CDI)	P200A21	The charge movement flap (cylinder bank 1) has a malfunction.The signal amplitude is less than the minimum amplitude.	STORED
IRS-HLA - Outer Left Rear Intelligent Radar Sensor system(B29/4)	580400	Component ''B29/4 (Left rear bumper intelligent radar sensor)'' is disrupted by interference from an external transmitter.	STORED
Audio/COMAND - Audio Or COMAND(A2-A2/56-A40/3)	c146	Communication with the central gateway has a malfunction.	STORED
IC - Instrument cluster(A1)	U015987	Communication with PARKTRONIC has a malfunction.The message is missing.	CURRENT and STORED